

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080036-4

No. 11389

RECEIVED FROM

PLANT #9

DATE REC'D. 2-27-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT

DRAWING

DWG. DASH OR

DWG.

LOT

CLASS

OPER

BUY OUT

ACCT. CR

W.O. NO.

S.O. NO.

CHANGE TO  
QUANTITY  
RECEIVED

323

254

0

20

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

105 780180 4 Nut AN 365-420-44-28

105

IPS #AOC3323

*[Signature]*

*[Signature]*

RECEIVED  
BYINSPECTED  
BY

Dura

DATE

2/5/57

REJECTS RETURNED  
ON SHIP. MEMO NO.

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2761 E. COLORADO ST., PASADENA, CALIF.

No. 11415

RECEIVED FROM

PLANT #9

DATE REC'D. 2-28-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT

DRAWING

DWG. DASH OR

DWG.

LOT

CLASS

OPER

BUY OUT

ACCT. CR

W.O. NO.

S.O. NO.

CHANGE TO  
QUANTITY  
RECEIVED

322

NCT-L

28

0

10

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

10 737329 Base Plate

10

To supersede RIR 11345

IPS #AOC3397

*[Signature]*

*[Signature]*

RECEIVED  
BYINSPECTED  
BY

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080036-4

HMC-108